

<b>ØD</b>	<b>C</b>	<b>ØH</b>	<b>Z</b>	<b>CÓDIGO</b>	<b>VALOR</b>
40	70	20	Z2+2 (22p)	FDH WD 407020-2-2	CONSULTE
50	62	20	Z2+2 (20p)	FDH WD 506220-2-2	CONSULTE
50	68	20	Z2+2 (24p)	FDH WD 506820-2-2	CONSULTE
50	100	20	Z2+2 (32p)	FDH WD 5010020-2-2	CONSULTE

<b>ØD</b>	<b>C</b>	<b>ØH</b>	<b>Z</b>	<b>CÓDIGO</b>	<b>VALOR</b>
18	30/54	16	Z3+3 (15p)	FDH WD 18305416-3-3	CONSULTE
18	35/65	16	Z3+3 (18p)	FDH WD 18356516-3-3	CONSULTE
20	30	20	Z3+3 (15p)	FDH WD 203020-3-3	CONSULTE
22,8	51	20	Z3+3 (27p)	FDH WD 22.855120-3-3	CONSULTE
25	53	25	Z3+3 (27p)	FDH WD 255325-3-3	CONSULTE
25	64	25	Z3+3 (33p)	FDH WD 256425-3-3	CONSULTE
30	47	25	Z3+3 (25p)	FDH WD 304725-3-3	CONSULTE
30	64	25	Z3+3 (35p)	FDH WD 306425-3-3	CONSULTE
42	41	20	Z3+3 (24p)	FDH WD 424120-3-3	CONSULTE
42	64	25	Z3+3 (36p)	FDH WD 426425-3-3	CONSULTE
48	38	20	Z3+3 (27p)	FDH WD 483820-3-3	CONSULTE
48	68	20	Z3+3 (48p)	FDH WD 486820-3-3	CONSULTE
48	85	20	Z3+3 (60p)	FDH WD 488520-3-3	CONSULTE
50	63	25	Z3+3 (44p)	FDH WD 506325-3-3	CONSULTE
50	108	25	Z3+3 (69p)	FDH WD 5010825-3-3	CONSULTE
53	30	25	Z3+3	FDH WD 533025-3-3	CONSULTE